

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

440  
ENE  
1/2-1  
0.694 mi.  
3664 ft.

**SPILL NUMBER 8905426**  
**2850 SHORE PARKWAY**  
**BROOKLYN, NY**

**NY LTANKS S106703370**  
**N/A**

**Relative:**  
**Higher**

**Actual:**  
**9 ft.**

**LTANKS:**

Name: SPILL NUMBER 8905426  
Address: 2850 SHORE PARKWAY  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 8905426 / 2003-04-09  
Facility ID: 8905426  
Site ID: 172243  
Spill Date: 1989-09-01  
Spill Cause: Tank Test Failure  
Spill Source: Commercial/Industrial  
Spill Class: C4  
Cleanup Ceased: Not reported  
SWIS: 2401  
Investigator: JMROMMEL  
Referred To: Not reported  
Reported to Dept: 1989-09-01  
CID: Not reported  
Water Affected: Not reported  
Spill Notifier: Tank Tester  
Last Inspection: Not reported  
Recommended Penalty: False  
Meets Standard: False  
UST Involvement: False  
Remediation Phase: 0  
Date Entered In Computer: 1989-09-05  
Spill Record Last Update: 2003-05-12  
Spiller Name: Not reported  
Spiller Company: Not reported  
Spiller Address: Not reported  
Spiller County: 001  
Spiller Contact: Not reported  
Spiller Phone: Not reported  
Spiller Extension: Not reported  
DEC Region: 2  
DER Facility ID: 144967  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was ROMMEL 03/06/2003- Closed Due To The Nature / Extent Of The Spill Report Formerly Battista Spill. 2/12/03Submittal From R&C Management Co (Irving Cohen). Tanks Retested After Repair On 11/8/89 By Horner Ez3 Passed. Rommel2/19/03Letter Mailed To Irving Cohen At 139-15 243Rd Street, Rosedale Ny 11422 Requiring Borings. Rommel03/18/03Soil Samples Collected By Winston From Three Borings 8-12 Feet Below Grade At Watertable. Svoc And Voc Analysis Results Acceptable For Closure. Rommel"

Remarks: "7.5K TANK FAILED HORNER EZY CHECK WITH A GROSS LEAK, SUSPECT FILL LINE."

**All TTF:**

Facility ID: 8905426  
Spill Number: 8905426  
Spill Tank Test: 1535955  
Site ID: 172243  
Tank Number: Not reported  
Tank Size: 0

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Material: 0001  
EPA UST: Not reported  
UST: Not reported  
Cause: Not reported  
Source: Not reported  
Test Method: 00  
Test Method 2: Unknown  
Leak Rate: .00  
Gross Fail: Not reported  
Modified By: Spills  
Last Modified Date: Not reported

All Materials:

Site ID: 172243  
Operable Unit ID: 930641  
Operable Unit: 01  
Material ID: 445860  
Material Code: 0001A  
Material Name: #2 fuel oil  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: -1.00  
Units: L  
Recovered: .00  
Oxygenate: Not reported